






Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is shown next to a circular inset containing an L-shaped metal bracket and a crossed-out power drill icon, indicating that a power drill should not be used for this step.
- Warning 2:** A second warning triangle with an exclamation mark is shown next to a circular inset containing a rectangular block being placed on a textured surface and a crossed-out icon of the block being placed on a smooth surface, indicating that the block must be placed on a textured surface.
- Time:** A clock icon is shown next to the text "15'", indicating a 15-minute assembly time.
- Person:** A stick figure icon is shown next to the number "1", indicating that one person is required for assembly.




<p style="text-align: center;"><b>A</b></p>  <p style="text-align: center;"><b>x 1</b></p>	<p style="text-align: center;"><b>B</b></p>  <p style="text-align: center;"><b>x 1</b></p>	<p style="text-align: center;"><b>C</b></p>  <p style="text-align: center;">M6 x 25</p> <p style="text-align: center;"><b>x 2</b></p>
---	---	--






**A**



**B**

<p style="text-align: center;"><b>D</b></p>  <p style="text-align: center;">M6 x 30</p> <p style="text-align: center;"><b>x 2</b></p>	<p style="text-align: center;"><b>E</b></p>  <p style="text-align: center;"><b>x 4</b></p>	<p style="text-align: center;"><b>F</b></p>  <p style="text-align: center;"><b>x 1</b></p>
--	---	---

1



2

