

CERRETO









Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing:
 - An icon of an L-shaped metal bracket.
 - An icon of a power drill with a diagonal line through it, indicating that a power drill should not be used.
- Warning 2:** A warning triangle with an exclamation mark is positioned above a box containing:
 - An icon of a rectangular block being placed on a textured surface.
 - An icon of a rectangular block with a diagonal line through it, indicating that the block should not be placed on a soft or uneven surface.
- Time:** A clock icon with a circular arrow indicates a duration of **15'**.
- Personnel:** An icon of a person indicates that **1** person is required for the task.




A1




x 1

A2




x 1

A3




x 1

A4




x 1

A5




x 1

A6




x 1

A7




x 1

1




x 2

2




x 4

3





x 2

4





x 1

1





2



3


2
M6
x
40
x 4

4
x 1



4

A5
x 1






5

1
M6
x
60
x 2


3
M6
x
25
x 2

4
x 1




6

A6
x 1




7

A7



x 1

A7



!

